

## **Request For Information** 24-283-003

Feb 5, 2025

Project Name Project Address

SDM 1112 WINDSOR 5050 TECUMSEH RD EAST, BUILDING 3, WINDSOR, ONTARIO

To From

Name

JEREMY DAVIS PAUL LEDDY
Company Company

LESTER CONSTRUCTION GROUP INC. Consult Mechanical Inc.

Email Email

jeremy@lestergroup.ca paul.l@consultmechanical.com

Address Address

3445 Wheelton Road, Unit 130, Windsor, Ontario N8W 5A6 54 Audia Court, Unit 2 Concord, ON L4K 3N5

Title SCHEDULE IMPACT COST IMPACT

Relocate Duct at main entrance No No

**RETURN BY** Feb 12, 2025

## **Information Requested**

There is an expansion joint that is located right where the return duct runs to the main entrance Can we offset to the left by 12 inches in order to miss the joint See attached Picture