

Request For Information 24-277-021

Apr 15, 2025

Project Name Project Address

YORK REGION VARIOUS PROJECTS 17250 Young Street Newmarket, ON

To From

Name Name

Tom Butkovic PAUL LEDDY

Company

TRISECT CONSTRUCTION Consult Mechanical Inc.

Email Email

tbutkovic@trisectconstruction.com paul.l@consultmechanical.com

Address

4020A SLADEVIEW CRESCENT, UNIT 7 MISSISSAUGA, ON L5L 6B1 JOB: 1300 INSLINGTON SUITE 103

54 Audia Court, Unit 2 Concord, ON L4K 3N5

Title SCHEDULE IMPACT COST IMPACT

Condensate Routing Fourth floor No No No

RETURN BY Apr 18, 2025

Information Requested

the condensate drains for the 4th floor between stairwells #3 and #2 do not work how they have proposed on the drawing. They show all the new condensate drains connecting into one storm drain. This storm drain does not run as shown on the drawing, and the height of it is our main issue. As it stands right now we can only connect one Fan coil condensate drain into the proposed drain.

One option for us to run is take a couple condensate mains back into the corridor where the condensate drain is being deleted. We would still be deleting further down the line, and we would still cap the take offs where the old condensates were tied in.