

Request For Information 24-229-011

Apr 16, 2025

Project Name Project Address

2299 DUNDAS - SHELTER RENOVATION 2299 Dundas Street West, Toronto, ON

To From

Name Name

Paddy Devlin ADNAN KHAN

Company

ROSSCLAIR CONTRACTORS INC. Consult Mechanical Inc.

Email Email

adnan@consultmechanical.com

Address

59 COMSTOCK ROAD, UNIT 1 TORONTO, ON M1L 2G6 54 Audia Court, Unit 2 Concord, ON L4K 3N5

Title SCHEDULE IMPACT COST IMPACT

Request for information for the access door of grease interceptor

Probable

Probable

RETURN BY Apr 24, 2025

Information Requested

As per the site conditions, it is not feasible to flush the cover of the grease interceptor with the finished floor level due to the floored slope. To address this issue, it has been proposed to provide a separate cover plate on top of the grease interceptor.

However, in the absence of any specific detail or specification in the project documentation, we kindly request your guidance in providing the necessary specification or detail for the required checkered cover plate, including material, thickness, load capacity, and installation method (if applicable).