

## **Request For Information** 23-214-026

May 12, 2025

Project Name Project Address

CHRIS GIBSON REC CENTRE 125 McLaughlin Rd N, Brampton, ON, L6X 1N9

To From

Name Name

Ashish Singla PAUL LEDDY

Company

RAFAT GENERAL CONTRACTOR INC. Consult Mechanical Inc.

Email Email

asingla@corebuildconstruction.com paul.l@consultmechanical.com

Address

8850 GEORGE BOLTON PKWY BOLTON, ON L7E 2Y4 54 Audia Court, Unit 2 Concord, ON L4K 3N5

Title SCHEDULE IMPACT COST IMPACT

Roof Fan interference with Steel Bracing No Probable

**RETURN BY** May 19, 2025

## **Information Requested**

There's two curbs for the mushroom fans that have structural bracing on the underside of the roof with there location causes structural interference with the galvanized beams on the outside of the roof.

See attached Photos

Suggestion: Underside Steel Reinforcing will need to be moved so openings can be shifted